

## **Entrapment, Suffocation Risks Prompt Recall of Certain PeaPod Travel Tents Prior To Year 2012**

To see the actual alert from the CPSC, [please click here](#).

- Product:** PeaPod Lite: P001 (Canada only)  
PeaPod Models: P100, P101, P102, P103, P104  
PeaPod Plus Models: P201, P202, P203, P204, P205, P900CS
- Hazard:** Infants and young children can roll off the edge of the inflatable mattress, become entrapped between the mattress and the fabric sides of the tent, and suffocate.
- Incidents/Injuries:** 3 incidents in Canada and 6 in the U.S. with no injuries and one death, where cause of death is reported as ‘undetermined’
- Remedy:** To receive a repair kit that includes a thinner replacement air mattress and braces that will strengthen the sides of certain models, fill out the form below and submit to KidCo. The recall only covers certain models prior to year 2012 and does not apply to newer KidCo PeaPod/PeaPod Plus.

Name: \_\_\_\_\_

Street Address: \_\_\_\_\_

Address (Line 2): \_\_\_\_\_

City: \_\_\_\_\_

State / Province / Region: \_\_\_\_\_

Zip Code / Postal Code: \_\_\_\_\_

Daytime / Evening Telephone: \_\_\_\_\_

E-Mail Address: \_\_\_\_\_

**In order for your PeaPod Repair Kit to be shipped you will need to include an image of the product  
AND fabric tag showing model number or original proof of new purchase.**

Mail All Requests To:

**KidCo, Inc.  
Attn: PeaPod Kit Department  
1013 Technology Way  
Libertyville, IL 60048  
United States of America**